

HDPE PIPE FUSION TROUBLESHOOTING GUIDES

BUTT FUSION TROUBLESHOOTING GUIDE	
Observed Condition	Possible Cause
<ul style="list-style-type: none"> Excessive double bead width 	<ul style="list-style-type: none"> Overheating Excessive joining force
<ul style="list-style-type: none"> Double bead v-groove too deep 	<ul style="list-style-type: none"> Excessive joining force Insufficient heating Pressure during heating
<ul style="list-style-type: none"> Flat top on bead 	<ul style="list-style-type: none"> Excessive joining force Overheating
<ul style="list-style-type: none"> Non-uniform bead size around pipe 	<ul style="list-style-type: none"> Misalignment Defective heating tool Worn equipment Incomplete facing
<ul style="list-style-type: none"> One bead larger than the other 	<ul style="list-style-type: none"> Misalignment Component slipped in clamp Worn equipment Heating iron does not move freely in the axial direction Defective heating tool Incomplete facing Also possible when fusing bimodal pipes to unimodal pipes
<ul style="list-style-type: none"> Beads too small 	<ul style="list-style-type: none"> Insufficient heating Insufficient joining force
<ul style="list-style-type: none"> Bead not rolled over to surface 	<ul style="list-style-type: none"> Shallow v-groove – Insufficient heating & insufficient joining force Deep v-groove – Insufficient heating & excessive joining force Bead on bimodal pipe may have slight gap to the pipe surface
<ul style="list-style-type: none"> Beads too large 	<ul style="list-style-type: none"> Excessive heating time
<ul style="list-style-type: none"> Square type outer bead edge 	<ul style="list-style-type: none"> Pressure during heating
<ul style="list-style-type: none"> Rough, sandpaper-like, bubbly, or pockmarked melt bead surface 	<ul style="list-style-type: none"> Hydrocarbon (gasoline vapors, spray paint fumes, etc.) contamination

SADDLE FUSION TROUBLESHOOTING GUIDE	
Observed Condition	Possible Cause
<ul style="list-style-type: none"> • Non-uniform bead size around fitting base 	<ul style="list-style-type: none"> • Misalignment • Defective heating tool • Fitting not secured in heating tool • Heating temperature not within specified range
<ul style="list-style-type: none"> • One bead larger than the other 	<ul style="list-style-type: none"> • Misalignment • Heating temperature not within specified range • Fitting slipped in clamp • Defective or worn equipment
<ul style="list-style-type: none"> • Beads too small 	<ul style="list-style-type: none"> • Insufficient heating • Insufficient joining force
<ul style="list-style-type: none"> • Beads too large 	<ul style="list-style-type: none"> • Excessive heating time • Excessive joining force
<ul style="list-style-type: none"> • Absence of third bead, or third bead widely separated from center bead 	<ul style="list-style-type: none"> • Incorrect pipe main heating tool • Insufficient joining force
<ul style="list-style-type: none"> • Pressurized main blowout (beside base or through fitting base) 	<ul style="list-style-type: none"> • Excessive heating • Heating temperature not within specified range • Incorrect heating tool faces • Excessive time to start heating or in joining the fitting to the main pipe after heating time cycle
<ul style="list-style-type: none"> • Rough, sandpaper-like, bubbly, or pockmarked melt bead surface 	<ul style="list-style-type: none"> • Hydrocarbon (gasoline vapors, spray paint fumes, etc.) contamination



SOCKET FUSION TROUBLESHOOTING GUIDE

Observed Condition	Possible Cause
<ul style="list-style-type: none"> • No evidence of cold-ring impression in socket fitting melt bead 	<ul style="list-style-type: none"> • Insufficient heating time • Depth gauge not used • Cold ring not used • Cold ring set at incorrect depth
<ul style="list-style-type: none"> • Gaps or voids around the pipe at the socket fitting edge 	<ul style="list-style-type: none"> • Pipe or fitting not removed straight from heater face • Components not joined together straight when fusing • Cold ring not used • Cold ring set at incorrect depth
<ul style="list-style-type: none"> • Wrinkled or collapsed pipe end 	<ul style="list-style-type: none"> • Cold ring not utilized • Cold ring set at incorrect depth • Incorrect heating sequence
<ul style="list-style-type: none"> • Voids in fusion bond area 	<ul style="list-style-type: none"> • Pipe or fitting not removed straight from heater face • Components not joined together straight when fusing • Cold ring not used • Cold ring set at incorrect depth
<ul style="list-style-type: none"> • Unbonded area on pipe at end of pipe 	<ul style="list-style-type: none"> • Cold ring not used • Cold ring set too deep
<ul style="list-style-type: none"> • Socket melt extends past end of pipe 	<ul style="list-style-type: none"> • Cold ring set too shallow
<ul style="list-style-type: none"> • Rough, sandpaper-like, bubbly, or pockmarked melt bead surface 	<ul style="list-style-type: none"> • Hydrocarbon (gasoline vapors, spray paint fumes, etc.) contamination

